


Location of Elements of a Welding Symbol



Basic Welding Symbols and Their Location Significance

Location Significance	Fillet	Plug or Slot	Spot or Projection	Stud	Seam	Back or Backing	Surfacing	Edge
Arrow Side								
Other Side				Not Used			Not Used	
Both Sides		Not Used	Not Used	Not Used	Not Used	Not Used	Not Used	
No Arrow Side or Other Side Significance	Not Used	Not Used		Not Used		Not Used	Not Used	Not Used
Location Significance	Groove							Scarf for Brazed Joint
	Square	V	Bevel	U	J	Flare-V	Flare-Bevel	
Arrow Side								
Other Side								
Both Sides								
No Arrow Side or Other Side Significance		Not Used	Not Used	Not Used	Not Used	Not Used	Not Used	Not Used



TECHNICAL SUPPORT

HIL BAX TECHNICAL CENTER : 314-644-3500

**HEADQUARTERS
ST. LOUIS, MO**

5835 MANCHESTER AVE ST. LOUIS, MO 63110
PHONE: (314) 644-3500 FAX: (314) 644-4336

O'FALLON, MO

VILLA RIDGE, MO

WOOD RIVER, IL

O'FALLON, IL

JOPLIN, MO

KANSAS CITY, MO

RETAIL

RETAIL

RETAIL

RETAIL

DRY ICE ONLY

DRY ICE ONLY

927 West Terra Lane
O'Fallon, MO 63366
(636) 272-3400

3286 Highway 100
Villa Ridge, MO 63089
(636) 451-2185

305 Old St. Louis Rd.
Wood River, IL 62095
(618) 254-4090

1360 Frontage Rd.
O'Fallon, IL 62269
(618) 624-9001

2015 Stephens Blvd
Joplin, MO 64804
(417) 501-9941

1234 Quebec St
Kansas City, MO 64116
(816) 423-1702